

PRO-SERIES CARBIDE + G1298 DIE SETS - Pro-Series Carbide Die Set 500 S&W Magnum

For those of you who want the best in pistol dies consider a Redding Titanium Carbide Set. Titanium Carbide has the highest hardness of any readily available carbide and provides a slick, non-galling surface. The price is a little higher but no lubrication is needed and your cases will glide through the sizing die. Pro Series Pistol Die Sets are designed for use in progressive reloading machines. The expander die is eliminated from the set and a separate crimp die is substituted. The set includes a carbide sizing die, bullet seater (no crimp type), and a separate crimp die.

NO IMAGE
AVAILABLE

Attributes

- Name: Pro-Series Carbide Die Set 500 S&W Magnum
- Manufacturer: REDDING
- Product no.: 749007311L
- Mfr. No.: 89291
- Cartridge: 500 S&W
- Die Style: Sizing Dies
- Delivery weight: 0.712kg
- UPC: 611760892912

Item details

Made in USA

Table of Contents

- [Startpage](#)
- [English: Safety Instruction Guide for ProSeries Carbide + G1298 Die Sets](#)
- [Italiano: PROSERIES CARBIDE + G1298 DIE SETS Manual di Istruzioni per la Sicurezza](#)

Safety Instruction Guide for ProSeries Carbide + G1298 Die Sets

Introduction

Thank you for choosing the ProSeries Carbide Die Set for your reloading needs. This guide provides essential safety instructions and guidelines to ensure the safe and effective use of your die set. Please read this manual carefully before use and keep it for future reference.

General Safety Guidelines

To ensure safe use of the ProSeries Carbide Die Set, please follow these general safety guidelines:

- Always wear appropriate protective gear, including safety glasses and gloves, when handling reloading equipment.
- Keep the workspace clean and organized to prevent accidents.
- Ensure that the die set is used only for its intended purpose.
- Store the die set in a secure location, out of reach of children and pets.
- Regularly inspect the die set for any signs of wear or damage before use.
- Follow all local laws and regulations regarding reloading and ammunition.

Specific Safety Precautions for Use

When using the ProSeries Carbide Die Set, please adhere to the following safety precautions:

- Ensure that the reloading press is securely mounted and stable before use.
- Do not exceed the recommended load specifications for the 500 S&W Magnum cartridge.
- Avoid distractions while reloading; focus on the task at hand.
- Do not use the die set if you are tired or under the influence of drugs or alcohol.
- Use only highquality components and materials compatible with the die set.
- Keep all reloading materials, including primers and powder, stored safely and away from heat sources.

Instructions for Installation and Usage

To ensure proper installation and usage of the ProSeries Carbide Die Set, follow these steps:

1. Installation:

- Securely mount the reloading press on a stable surface.
- Select the appropriate die from the set: carbide sizing die, bullet seater (no crimp type), and separate crimp die.
- Install the carbide sizing die into the press according to the manufacturer's instructions.
- Adjust the die to the correct height for sizing the 500 S&W Magnum cartridge.

2. Usage:

- Begin by preparing your cases for reloading. Ensure they are clean and free from debris.
- Insert the case into the sizing die and operate the press to size the case.
- After sizing, remove the case and proceed to the bullet seating process.
- Insert the bullet into the case and place it into the bullet seater die.
- Operate the press to seat the bullet to the desired depth.
- Finally, use the separate crimp die to apply a crimp if necessary.

Disposal Instructions

When disposing of the ProSeries Carbide Die Set or any components, please follow these guidelines:

- Dispose of the die set in accordance with local regulations for metal recycling.
- Do not dispose of any reloading materials, such as primers or powder, in regular trash.
- Contact local waste management authorities for proper disposal methods of hazardous materials.

Contact Information for Further Support

For any questions or concerns regarding the ProSeries Carbide Die Set, please refer to the manufacturer's contact information provided with your product. Ensure to reach out for assistance, product inquiries, or safety concerns.

Thank you for choosing the ProSeries Carbide Die Set. Your safety is our priority, and we hope you enjoy your reloading experience.

PROSERIES CARBIDE + G1298 DIE SETS Manual di Istruzioni per la Sicurezza

Introduzione

Grazie per aver scelto il set di die in carburo ProSeries per il 500 S&W Magnum. Questo manuale fornisce istruzioni importanti per garantire un utilizzo sicuro e corretto del prodotto. Si prega di leggere attentamente queste informazioni prima di utilizzare il set.

Linee Guida Generali per la Sicurezza

- Assicurarsi che il prodotto sia utilizzato solo per l'uso previsto.
- Tenere il set lontano dalla portata dei bambini e di altri gruppi vulnerabili.
- Controllare regolarmente il prodotto per eventuali segni di usura o danni.
- Seguire sempre le istruzioni del produttore per l'uso e la manutenzione.
- Segnalare eventuali prodotti non sicuri o incidenti alle autorità competenti.

Precauzioni di Sicurezza Specifiche per l'Uso

- Utilizzare sempre occhiali protettivi durante l'uso del set di die.
- Indossare guanti protettivi per evitare lesioni alle mani.
- Non forzare mai il die durante l'operazione di dimensionamento o crimpatura.
- Assicurarsi che la macchina di ricarica sia ben fissata e stabile prima di iniziare l'operazione.
- Non utilizzare il set di die se si notano parti danneggiate o difettose.

Istruzioni per l'Installazione e l'Uso

Installazione

1. Assicurarsi che la macchina di ricarica sia spenta e scollegata dalla fonte di alimentazione.
2. Montare il die di dimensionamento in carburo nella macchina di ricarica seguendo le istruzioni del produttore.
3. Fissare il die di crimpatura separatamente in modo sicuro nella posizione designata.
4. Installare il seghetto di proiettili (tipo senza crimpatura) come indicato nel manuale della macchina.

Uso

- Verificare che il bossolo sia pulito e privo di detriti prima di inserirlo nel die.
- Posizionare il bossolo nel die di dimensionamento e attivare la macchina di ricarica.
- Dopo il dimensionamento, rimuovere il bossolo e controllare che sia stato dimensionato correttamente.
- Procedere con il seghetto di proiettili seguendo le istruzioni specifiche per il tipo di proiettile utilizzato.
- Infine, utilizzare il die di crimpatura per completare il processo di ricarica.

Istruzioni per lo Smaltimento

- Non smaltire il set di die nel normale rifiuto domestico.
- Seguire le normative locali per lo smaltimento dei materiali metallici e dei prodotti per la ricarica delle munizioni.
- Contattare un centro di raccolta locale per informazioni su come smaltire in modo sicuro i materiali pericolosi.

Informazioni di Contatto per Ulteriore Supporto

Per ulteriori informazioni sulla sicurezza del prodotto o per segnalare un problema, contattare il punto di contatto locale dell'Unione Europea.

Si prega di conservare questo manuale per riferimento futuro. La sicurezza è la nostra priorità, e il corretto utilizzo di questo prodotto contribuirà a garantire un'esperienza di ricarica sicura e soddisfacente.